

700 West Mineral Ave  
Littleton, CO 80120



## Network Disclosure Announcement No. 778

Short Term Public Notice Under Rule 51.333(a)

CenturyLink's Internet address: <http://qwest.centurylink.com/disclosures/>

### Copper Retirements in Arizona, Iowa, South Dakota, and Washington.

**First Implementation Date:** *September 1, 2014*

Original Date Posted:

July 7, 2014.

**Summary:**

Copper Retirements are necessary to respond to various factors in the Outside Plant, including road construction, maintenance problems, and growth accommodation. Replacement cables may be either copper or fiber. Specific information will be provided with each disclosure.

**Locations, Timing of  
Deployments & Interface  
Requirements:**

The following gives additional details on the copper retirement(s):

STATE	WIRE CENTER	PLANNED COMPLETION OR RETIREMENT DATE	DA (s)	Job #	Replacing
AZ	Tucson North TCSNAZNO	09-30-2014	212111	E.296080	Road move in the area requires requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.

STATE	WIRE CENTER	PLANNED COMPLETION OR RETIREMENT DATE	DA (s)	Job #	Replacing
IA	Dubuque DUBQIATC	09-01-2014	122202	E.419163	Road move in the area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.
SD	Sioux Falls SXFLSDCO	09-15-2014	411505	E.657323	Growth in distribution area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.
WA	Bremerton BMTNWA01	09-26-2014	160201	E. 635824	Growth in distribution area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.

**Additional Information:**

Any customer premises equipment vendor/manufacturer or enhanced services provider desiring additional technical information in conjunction with this Disclosure can contact:

Abdennaceur Boudhaouia  
Regulatory Compliance Manager  
303-707-8561 [Jamal.Boudhaouia@CenturyLink.com](mailto:Jamal.Boudhaouia@CenturyLink.com)

