

700 West Mineral Ave  
Littleton, CO 80120



*Network Disclosure Announcement No. 782*

Short Term Public Notice Under Rule 51.333(a)

**CenturyLink's Internet address: <http://www.centurylink.com/disclosures/>  
Copper Retirements in Arizona, Iowa, and Minnesota.**

**First Implementation Date:** *June 15, 2015*  
**Original Date Posted:** *March 27, 2015*

**Summary:** Copper Retirements are necessary to respond to various factors in the Outside Plant, including road construction, maintenance problems, and growth accommodation. Replacement cables may be either copper or fiber. Specific information will be provided with each disclosure.

**Locations, Timing of  
Deployments & Interface  
Requirements:**

The following gives additional details on the copper retirement(s):

| STATE | WIRE CENTER                   | PLANNED COMPLETION OR RETIREMENT DATE | DA (s)                 | Job #    | Replacing  |
|-------|-------------------------------|---------------------------------------|------------------------|----------|--|
| AZ    | Tucson<br>Cortaro<br>TCSNAZCO | 06-15-2015                            | 212011; 212014; 212412 | E.714051 | Growth in distribution area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available. |

| STATE | WIRE CENTER              | PLANNED<br>COMPLETION<br>OR<br>RETIREMENT<br>DATE | DA (s)         | Job #    | Replacing  |
|-------|--------------------------|---|----------------|----------|--|
| AZ    | Mesa Main<br>MESAAZMA    | 06-26-2015  | 114021         | E.723502 | Growth in distribution area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available. |
| IA    | Storm Lake<br>STLKIATC   | 07-07-2015  | 422106: 422108 | E.737383 | Growth in distribution area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available. |
| MN    | Fergus Falls<br>FRFLMNFB | 06-15-2015  | 180402         | E.616625 | Road move in the area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.       |

| STATE | WIRE CENTER         | PLANNED<br>COMPLETION<br>OR<br>RETIREMENT<br>DATE | DA (s) | Job #    | Replacing  |
|-------|---------------------|---|--------|----------|--|
| MN    | Willmar<br>WLMRMNWI | 07-31-2015  | 31302  | E.720857 | Growth in distribution area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available. |

**Additional Information:**

Any customer premises equipment vendor/manufacturer or enhanced services provider desiring additional technical information in conjunction with this Disclosure can contact:

Abdennaceur Boudhaouia  
Regulatory Compliance Manager  
303-707-8561  
[Jamal.Boudhaouia@CenturyLink.com](mailto:Jamal.Boudhaouia@CenturyLink.com)